

United States Steel Corporation Clairton Works 400 State Street Clairton, PA 15025

42-003-00032 APC4=0 ATP=00COUTAGE ROT) 03-09-18

September 18, 2003

Dr. Roger C. Westman Department of Air Quality Bureau of Air Pollution Control 301 Thirty-Ninth Street Pittsburgh, PA 15201

Assistant Council Southwest Region 400 Waterfront Drive Pittsburgh, PA 15222-4745 ATTN: Steve Hepler

U.S. Environmental Protection Agency Region III Air, Radiation & Toxics Division 1650 Arch Street Philadelphia, PA 19103-2029 ATTN: Michael Ioff (3AT23)

Department of Justice Department of Environmental Protection Environmental and Natural Resource Division Environmental Enforcement Section P.O. Box 7611 Ben Franklin Station Washington, D.C. 20044 ATTN: David Street, Esq.

Subject: USS Reference Number: 03-0097

ACHD Reference Number: 4619

#2 Control Room USS Clairton Works

Gentlemen:

The attached form confirms our verbal report of the subject incident. Any questions concerning this matter should be referred to Coleen M. Davis at 233-1015.

Sincerely,

Anton Lukac Plant Manager Clairton Works

NOTICE OF OUTAGE OF EQUIPMENT ARTICLE XXI - SECTION 2108.1

- 1. USS Reference Number: 03-0097
- 2. Date & Time of Breakdown: Date: 09/17/03 Time: 1515 hours
- 3. Company Name: U.S. Steel Corporation USS Clairton Works
- 4. Specific Equipment Involved or Affected: #2 Control Room
- 5. BAPC Permit Number (if applicable):
- 6. Location: Clairton, PA
- 7. Nature and cause of breakdown: A leak in the expansion turbine piping has resulted in a reduced level of operation at the #2 Control Room and partial bypassing coke oven gas to the down river and under firing systems.
- 8. Identification of Emissions:
 - A. Type(s) (CO, NOX, SO_2 , Particulates, Hydrocarbons, etc.) Elevated H_2S in the downriver and under firing gas line systems, causing increased SO_2 and VOC at point of combustion.
 - B. Toxic qualities of each type (including its qualities as an irritant, and its potential for causing illness, disability, or mortality). SO_2 is and VOC could be an eye, nose, and throat irritant.
 - C. Amount of each type emitted (or likely to be emitted). Light to moderate
- 9. Measures taken (or to be taken) to minimize length of breakdown and amount of emissions, including shutdown or curtailment (or why it is impossible or impractical to do so).

 Repairs are underway and expected to be completed in approximately 3 4 days.
- 10. Facility back in operation Date: Time: hours

Signature (len) h. Juro Date 9/18/03

Coleen M. Davis

Senior Environmental Control Engineer Phone: 233-1015